


Part Number: **4160164xx-3**

Model: **HD-3000S**

DATE	VERSION	SUMMARY OF CHANGES	NOTE
13 October 2010	40	Production release HD-3000S Bare PCB: 016016004-3; P/N 416016440-3 BIOS: U17, V1.10.00 (AT45DB041D)(new) U19, V0.22.00 (Atmega324PA)	ECN# 870689201
25 March 2011	4x to 50	Use new PCB - Fix rework on previous PCB - Add SDI input bypass test point (X_BYPASS & Y_BYPASS) on board for customer usage  Bare PCB: 016016005-3; P/N 416016450-3 BIOS: U17, V1.10.00 (AT45DB041D)(no change) U19, V0.22.00 (Atmega324PA) (no change)	ECN# 870689230
25 June 2015	50 to 51	Upgrade firmware 1. Prevent loss of detection issue when connected with controller through I2C 2. Enable the 10bit processing officially(10bit input and 10bit HDMI output)(please make sure it connected to the monitor with HDMI interface which supports 10bit input signal) 3. Disable the range compression and range clip. 4. Fixed improper NTSC video output at HDMI output port. 5. Fixed wrong lock signal detection due to noise for some GS2970A IC, that will cause LED3 flashing occasionally when no input cable plug into to the BNCs. Bare PCB: 016016005-3; P/N 416016451-3 BIOS: U17, V1.10.00 (AT45DB041D)(no change) U19, V1.29.00 (Atmega324PA) (changed) File name : HD-3000_U19_1V2900_150626.zip	ECN# 870689514
19 December 2017	5x to 60	1. Change to use pin to pin compatible Equalizer chipset (Semtech GS2994-INTE3) used on U11 to replace the end of life Semtech GS2974B-CNTE3 Equalizer chipset. 2. Remove capacitor on C70 for using the new Semtech GS2994-INTE3 chipset. Bare PCB: 016016005-5; P/N 416016460-3 BIOS: U17, V1.10.00 (AT45DB041D)(no change) U19, V1.29.00 (Atmega324PA) (no change)	ECN# 870689680

Prepared by: DV-HK

Date: 19 Dec 2017